5. Error Message

The following error message will appear when incorrect operation is performed.

Massage	Remark	Solution
O F	When displayed weight exceeded capacity+9d, or there is some weight on platter when power on.	Remove some weight from platter
U F	When displayed minus weight <= - 9d	Re-Zero or On/Off again
8 8 8 8 8 8	A/D checking error or scale is not stable enough after powered on	Place scale on firm, flat base and make it level enough. Or calibrate it again
E R R O R	Calibration operation is not correct, or A/D checking error when power on	Repeat calibration operation.

Note: If you cannot solve the problem you met according to above solutions, please contact to our local service man.